




# Rhino Visual Tips 4.0

## Dimensions.

Learn how to dimension and annotate your drawings.




### Key things to remember.

Rhino 4.0 can provide the ability to add notation to your model in the form of dimensions, leaders, and text blocks. These appear as objects in the model. A different form of notation, the annotation dots and arrowheads, always display facing towards the view plane. Do not forget that now you can **Double Click** the text to edit it.



Learn how to create and save your own dimension styles. You will save a lot of time in the future by having these styles ready. New in Rhino 4.0 are the Ordinate dimensions. Try those too.



**Notes:** The dot command places a text dot. Dots are always parallel to the view. There isn't control for the dot size or shape. Dots are display in the layer color. Dot sizes are constant on the screen. Double click it to edit the content of the dot.